





3400 West "O" Street – Lincoln NE – 68528
Phone: 402-435-4249 - Fax 402-438-3918 - [Http://www.thunderstonemfg.com](http://www.thunderstonemfg.com)


Tarp Repair Kit Instructions

Warning: it must be at least 65° to repair tarp effectively.

1. Make sure that your kit # 035-39446 includes the following parts:
 - a. Tarp remnant
 - b. HH-66 Vinyl Cement (Quart)
 - c. HH-66 Thinner (Pint)
2. Rough up and clean area to be patched with soap and water to remove dirt and debris.
3. Cut patch to fit over tear in tarp. Patch should be at least 2" larger than the tear. Round off the corners of the patch to prevent snagging corners.



4. Center the patch over the tear on the underside of the tarp.
5. Trace around the patch to mark where the glue will be applied.
6. To make sure that the patch adheres properly clean an area 1" larger than the patch using the HH-66 Thinner
7. Apply glue to the marked area on the tarp and on the patch. Allow cement to dry 2 – 5 minutes or until it becomes tacky.
8. Press the patch on the underside of the tarp and allow glue to dry for 1 to 24 hours. HH-66 Vinyl Cement's strength will increase the longer it is allowed to dry.



To repair a circular tear:
Place the dull top side of fabric patch against the shiny bottom side of the tarp.